



# BLACK JACK DZ




Safety Box 100 yds from each DZ edge

# BLACK JACK DZ



# BLACK JACK DZ



	<b>Flight Lead</b>	<b>Wingman</b>	<b>Element Lead</b>
<b>Planning</b>	Must brief SCNS XTRK CONTRACT to the formation INTRK CONTRACT is $\pm 2$ seconds	Precalculate No-Drop parameters for SKE Position & Timing	
<b>Run-in</b>	Verify position using AWADS Pass SKE Commands “Fly the Bar”	Maintain SKE Position	Back up Lead Relay SKE Commands After SD “fly the bar”
<b>Airdrop</b>	Maintain Contract	Use actual INTRK at Lead’s <b>E</b> for timing After Hack maintain constant airspeed Drop off SKE Timing	Will maintain CARP & TWS XTRK within tolerance Verify INTRK at Lead’s <b>E</b> (subtract lead’s contract from INTRK safety box)